MEDINA PALMS RESIDENCE

PROGRESS REPORT OF 7/01/2012

	BLOCK	EXCAVATION	FOUNDTN WALLS & COL	RETAINING WALL	BACKFILLING	L. GROUND FLR. SLAB	L.GROUND FLR.WALLS	L.GROUND FLR.CLUMNS	GROUND FLR. SLAB	ARCHITECT'S CERT.	GROUND FLR WALLS	GROUND FLOOR COL	1ST FLOOR SLAB	ARCHITECT'S CERT.	1ST FLOOR WALLS	1ST FLOOR COLUMNS	2ND FLR SLAB/ ROOF TERRACE	ARCHITECT'S CERT.	2ND FLOOR WALLS	2ND FLOOR COLUMNS	ROOF SLAB	ROOF STRUCTURE	ROOF COVERING	WALL FINISHES								CEILING FINISHES				ELECTRICAL WORKS								PLUMBING WORKS							
																								INTERNAL				EXTERNAL								1st FIX				2nd FIX				1st FIX				2nd FIX			
																								LGF	GF	FF	SF/RT	LGF	GF	FF	SF/RT	LGF	GF	FF	SF/RT	LGF	GF	FF	SF/RT	LGF	GF	FF	SF/RT	LGF	GF	FF	SF/RT	LGF	GF	FF	SF/RT
	LOV 1	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%		100%	100%	100%		100%	100%	100%	50%			100%	100%	100%		100%	100%			100%	100%				50	50%							10%	10%					
	LOV 2	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	50%			100%	100%	100%		100%	100%			100%	100%				50%	50%							30%	10%					
	BV 3/4	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	50%			100%	100%	100%		100%	100%			100%	100%				50%	50%							75%	75	50%				
	BV 5/6	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	100%	100%		100%	100%	100%		100%	100%	100%		100%	100%	100%			50%	50%							80%	80%	75%		75%	75%	
	BV 7/8	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%	√	100%	100%	100%		100%	100%	100	75%			100%	100%	100%		100%	50%			100%	100%				50%	50%							70%	50%	30%		30%		
	BV 9/10	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	100%	50%		100%	100%	100%		100%	100%			100%	100%				50%	50%							70%	50%	30%				
13/14/23/24	OVA 13 /14	100%	100%	100%	100%	100%	100%	100%	100%		100%	100%	100%		100%	100%	50%		50%	50%				100%	100%	50%	25%									50%	50%							10%	10%	10%				
11/12/17/18/21/22	PA 11 / 12	100%	100%	100%	100%	100%	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	70%		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%		50%	50%	50%						10%	30%	20				
15/16/19/20/25/26	PA 15 / 16	100%	100%	100%	100%	100%	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	70%		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%		50%	50%	50%						310%	30%	10%				
28/32/27/31	MA 28 / 32	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	70%			100%	100%	100%		100%	100%	100%		100%	100%	100%	50%		50%	50%							50%	30%				
29/33/30/34	MA 29 / 33	100%	100%	100%	100%	100%	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	70%		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%		50%	50%	50%						10%	50%	10%				
36/40/35/39	MA 36 / 40	100%	100%	N/A	100%	N/A	N/A	N/A	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	70%			100%	100%	100%		100%	100%	100%		100%	100%	100%	50%		50%	50%							50%	30%				
37/41/38/42	MA 37 / 41	100%	100%	100%	100%	100%	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%	70%		100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%		50%	50%	50%						10%	50	10%				
44/48/47/43	MA 44 / 48	100%	100%	N/A	100%	N/A	N/A	N/A	100%		100%	100%	100%		100%	100%	100%	√	100%	100%	100%	70%			100%	100%	100%		100%	100%	100%		100%	50%				50%	30%							50%	20%				
45/49/50/46	MA 45 / 49	100%	100%	100%	100%	100%	100%	100%	100%	√	100%	100%	100%	√	100%	100%	100%		100%	100%	100%	80%		100%	100%	100%		100%	100%	100%	100%	100%	100%	100%		50%	50%	50%						10%	50%	50%				
	RESTAURANT	100%	100%	100%	100%	100%																																												
	U. WATER TANK	100%	100%	100%	100%	100%																																											
	BIO DIGESTER	100%	100%	100%	50%																																												